



High Back Dining Room Chair #1

Walt Akers ThanksGiving 1999


Directional Views of Assembled Chair







Exploded Views of Chair

- A) Front Leg
- B) Rear Leg
- C) Front Seat Rail
- D) Heel Rail
- E) Rear Seat Rail
- F) Lower Back Receiver
- G) Upper Back Receiver
- H) Rear Base Rail
- I) Back Side Panels
- J) Back Center Panel
- K) Side Seat Rail
- L) Lower Side Rail
- M) Base Side Panel
- N) Base Center Panel











Front


Side

















Front Seat Rail (1 each) / Rear Seat Rail (1 each)




Heel Rail (1 each) / Rear Base Rail (1 each)




Lower Back Receiver Rail



Side Seat Rail (2 each)



Lower Side Rails (2 each)



Upper Back Receiver

